

C.L. "BUTCH" OTTER - Governor RICHARD M. ARMSTRONG - Director

FILE COPY

DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Eider Street P.O. Box 83720 Boise, idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

April 3, 2007

Pat Gooding, Administrator Kuna Living Center 194 W White Way Kuna, ID 83634

License #: RC-763

Dear Ms. Gooding:

On February 13, 2007, a life safety code survey was conducted at Kuna Living Center. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

priville

EM/sc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

February 15, 2007

Pat Gooding, Administrator Kuna Living Center 194 W White Way Kuna, ID 83634

Dear Ms. Gooding:

On February 13, 2007, a life safety code survey was conducted at Kuna Living Center. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by March 15, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely.

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: A. BUILDING 01 - ENTIRE BUILDING B. WING 13R763 02/13/2007 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 194 W WHITE WAY **KUNA LIVING CENTER** KUNA, ID 83634 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on February 13, 2007. The surveyor conducting the survey was: Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety & Construction Program Bureau of Facility Standards TITLE (X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM 6899 J6Ri21 If continuation sheet 1 of 1



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

Facility I	Name ,		Physical Address	Phone Number		00000000000000000000000000000000000000
K	lung Lu	in Centu	194 West Cente Way	922	3536	
Administrator City ZIP Code						
Pat Grouding			/ < 10 m = 0	834	134	
Survey Teem Leader			i Survey i voe	Survey Date	,	
Enc Muntell			Fire/Li/e Solety	1 2/13/0	7	
NON-CORE ISSUES						
ITEM #	RULE# 16.03.22		DESCRIPTION	17.11		BFS USE
/	415.01	Equipment maintained:	Bux loover is missing from &	iw switch	4/2/7	m
,	,	10 6/dy # 3. (qu	tomate to extrince	Lon.	01 //	108-1150 E20
2	750.05a	Annual inspection / 6	ating: The results of an are alarm injections for blood an artiste by	nnual	4/2/7	يدع
		Insulation of the live	e alora Marctais for bl	d, 4/4.0		
		ulda # 2 were not	a lille to the day	1 4-	in 1	15 S (CE 152)
		had been inject.	De available 12 Joseph Fac by	many		
		p - f - f - f - f - f - f - f - f - f -	4			
**.						
	*					53.438.50
***************************************			<u>:</u>			
					and	
						3 43 56
	***************************************			~~~		
· · · · · · · · · · · · · · · · · · ·					F	5 (9.85)
Response Required Date		Signature of Facility Representative		·	Date Signed	
March 15, 2007		Ktal Sarke			2/13/07	}